



JON M. HUNTSMAN, JR.

Governor

GARY R. HERBERT

Lieutenant Governor

State of Utah


DEPARTMENT OF NATURAL RESOURCES

Division of Oil, Gas & Mining

MICHAEL R. STYLER
Executive Director

JOHN R. BAZA
Division Director

Inspection Report Minerals Regulatory Program October 26, 2010

Reviewed: 

Mine Name: Red Chief	Permit Number: S/015/0083
Operator Name: Quality Building Stone	Inspection Date: October 21, 2010
Inspector(s): Wayne Western	Time: 12:05 – 12:40 pm
Other Participants: Steve Miller	Mine Status: Inactive

Elements of Inspection	Evaluated	Comment	Enforcement
1. Permits, Revisions, Transfer, Bonds	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
2. Public Safety (shafts, adits, trash, signs, highwalls)	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
3. Protection of Drainages / Erosion Control	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
4. Deleterious Material	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
5. Roads (maintenance, surfacing, dust control, safety)	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
6. Concurrent Reclamation	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
7. Backfilling/Grading (trenches, pits, roads, highwalls, shafts, drill holes)	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
8. Water Impoundments	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
9. Soils	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
10. Re-vegetation	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
11. Air Quality	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
12. Other	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>

Purpose of Inspection:


The Division met with the Operator on site to discuss reclamation.

Inspection Summary:

The amount of reclamation that can be done at the site is limited due to the amount of bedrock at or near the surface. The Operator should spread the topsoil in areas so that there is a minimum depth of 6-8 inches. The Operator should also stabilize the channel as needed. The Operator should use judgment to restore site to a natural looking environment. The stockpile of boulder could be spread out and group in clumps to provide habitat for small animals.

Conclusions and Recommendations:

The Division should conduct a follow up inspection before the winter snows.

Inspector's Signature 

(WHW):

cc: (OPERATOR)

SITLA


O:\M015-Emery\S0150083-RedChief\inspections\ins-10212010.doc



Boulders



Soil stockpiles



Surrounding area



Drainage just before the disturbed area.